

Work Order ID 81256

Monday, March 12, 2012 2:40:01 PM

81256

Page 1

Item ID: D3319-3

Revision ID: U/R

Item Name: Wearplate

Start Date: 3/12/2012 Start Qty: 6.00

Required Date: 3/13/2012 Req'd Qty: 6.00

Reference: SCRAP

Accept

N900040100Setup Start ***NS1***Stop ***NS2***

Cust Item ID:

Customer:

Approvals: Process Plan: *mf*

QC:

Date: *12-03-12*

Date:

Tooling:

SPC (Y/N):

Date:

Date:

Run Start ***NR1***Stop ***NR2***Sequence ID/
Work Center IDOperation
DescriptionSet Up/
Run Hours

Tool ID

Tool #

Plan
CodeAccept
QtyReject
QtyReject
NumberInsp.
Stamp

Draw Nbr

Revision Nbr

D3319

Rev B U/R

230

0.00

230

Small Fab

Memo

0.00

Small Fab

PULL FROM STOCK D3319-3 X 6 B 77829

SCRAP AND DESTROY

240

QC21- Final Inspection - Work Order Release

0.00

240

QC

Memo

0.00

Quality Control

*12/23/12**12/31/13*

Picklist Print

Monday, March 12, 2012 2:40:00 PM

Page 1

Work Order ID: 81256
Parent Item: D3319-3
Parent Item Name: Wearplate

Start Date: 3/12/2012
Start Qty: 6.00

Required Date: 3/13/2012
Required Qty: 6.00

Comments: IPP: A05.05.12New issueKJ/JLM
IPP Rev:B Now on Waterjet 06-10-03 JLM

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Qty per Kit	Total Qty	Qty Issued	Date Issued	Status
D3319-3 Wearplate		Manufactured	No				Each	0.0000		6			

#77829 x 6 MF 12-03-12

12-03-13

6

List Lots

Monday, March 12, 2012 2:17:44 PM

Page 1 of 1

Criteria : Item ID: d3319-3 All Locations All Warehouses All Quantity

Item ID Item Name	Warehouse ID Location ID	Lot Number	Last Trans Date	Lot Qty	Shelf Life Dt Lot Code	Type Code	Comments
D3319-3 Wearplate	Main Warehouse ST497	77829	3/7/2012	6.0000	QC21		
			Total:	6.0000			